DEPARTMENT OF HEALTH SERVICES

714/744 P STREET SACRAMENTO, CA 95814



PRELIMINARY ASSESSMENT SUMMARY

Kern Front Oilfield East of Highway 65 North of Bakersfield Oildale, CA 93308

History and Problem:

This site has been occupied by oil wells for at least 30-40 years. Approximately 18 different oil company operators are located at the site.

For years, waste by-products of the oil production operation, including drilling muds, scrubber wastes, and production waste water, have been dumped into sumps adjacent to each drilling site. There are also some injection wells on-site which gave been used for disposal of drilling muds.

Although some drilling muds are considered to be hazardous wastes because they contain corrosive or toxic additives, the drilling muds which have been disposed at this site have not been found to be hazardous by either the California Department of Health Services (DHS) or the Central Valley Regional Water Quality Control Board (CVRWQCB). The CVRWQCB regularly inspects the sumps within this oilfield and requires monitoring of both groundwater and surface run off (which is reclaimed for irrigation). No water pollution problems have developed as a result of thes equifield operations.

The Kern front oil field lies in an arid region. There are no residential or recreational land uses nearby and little potential for waste migration.

Recommendation:

The local health department and Central Valley Regional Water Quality Control Board have been monitoring water quality near the oil feid and no major contamination problems have been identified. Since available information does not indicate hazardous wastes have been disposed onsite, no further investigation is recommended.

PRELIMINARY ASSESSMENT Region 9

٦,

Preparer's Name Linda Kruse

Date February 1984

| | | SOURCE | INFORMATION |
|-----|------------------------------------|---|--|
| 1. | Site ID Number | ERRIS Turnaround | CAD980695258 |
| 2. | Site Name | ERRIS Turnaround | Kern Front Oilfield |
| 3. | Site Location | EP A IX Form 824 November 3, 1982 | East of Hwy 65 north of Bakersfield |
| 4. | County | ERRIS Turnaround | Kern |
| 5. | Owner (Address & telephone no.) | EPA IX Form 824 November 3, 1982 | Chevron U.S.A. (805) 393-0847 Route 1, Kern River Oilfield Oildale, CA 93308 |
| 6. | Operator (Address & telephone no.) | EPA IX and RWQCB's Scott Smith See T/C memo dated 2/15/84 | There are 18 owner/operators Main ones are Getty Oil, Chevron, Petro-Lewis, Kressmont, Santa Fe; and Mobil Oil Company |
| 7. | Type of Ownership | Scott Smith 2715784 RWQCB | Private Oil Companies |
| 8. | Status | BWNGB BHS TBErDi | 7 |
| 9. | Source Activity | RWQCB See 2/15/84 memo of call | Oil field production drilling |
| 10. | Years of Operation | RWQCB-Scott Smit | n 1930s or 40s to present |
| 11. | Facility Type | 2/15/84 telephone contact with Scott Smith (RWQCB) | e Oilfield individual wells often sharing mud disposal/reclamation facilities No public access |
| 12. | Waste Type and Description | RWQCB T/C Scott Smith, 2/15/84 40 CFR 5-621 "hazardous waste criteria" | Drilling muds with bentonite and chromium additives, scrubber wastes, and production water. Each well drilled produces an unspecified amount of drilling mud which is often retained in nearby sumps. The mud is mostly water and soil and is not hazardous according to 40 CFR. |

| 13. | Contacts RWQCB Central Valley Scott Smith, (209) 445-5116; DHS Toxics Division, N. CA Section, Fresno, Mohinder Sandhu and Bill Haggi, (209) 861-6676; Kern Co. Health Dept., Bakersfield, Richard Casagrande, (805) 861-3636; DHS |
|-----------|--|
| | Toxic Division Dave Storm, (916) 324-1807 |
| 14. | Incidents |
| | None Recorded At Agencies Checked |
| | Fire and Explosion Direct Contact |
| 15. | Inspections (date, type, by whom, recommendations) |
| | No inspection information available at agencies checked |
| | |
| | |
| | |
| | |
| | |
| 16. | Enforcement History (list date, type of action, requirements, outcome) |
| | No records available |
| | |
| | |
| | |
| | |
| 17.a | . Initial recommendation for further action: |
| | No further action |
| | |
| 17.b | . EPA recommendation for further action: |
| | |
| | |
| 18. | Response Termination: No Further Action Pending Active |
| | Justification: Concur with DOHS findings and recommendation |
| | |
| | Thomas 6. n. |
| | 8/1/84 |
| EPA-I | There does not appear to be an uncontrolled 1/18/83 trongendous wester problem at the fail. it. No 1/18/83 buther coexcept action is required. Illou 5/15/35 |
| | Jurther CERCIA action is required. 11/16st 5/15/35 |

| | | SOURCE | INFORMATION |
|-----|--|----------------|-------------|
| 19. | Observed Release | | |
| 20. | Depth to Aquifer | | |
| 21. | Net Precipitation Net seas. rainfall Evaporation | | |
| 22. | Permeability of Unsaturated Zone | ,, ,, ,, | |
| 23. | Physical State | | |
| 24. | Containment (Ground Water) | | |
| 25. | Toxicity | | |
| 26. | Persistence | , | |
| 27. | Waste Quantity | | · |
| 28. | Ground Water Use | | |
| 29. | Distance to Well | | |
| 30. | Population Served (by Ground Water) | | |

| | | SOURCE | INFORMATION |
|-----|---|--------|---------------------------------------|
| 31. | Facility Slope | | |
| 32. | l yr. 24 hr. rainfall | | |
| 33. | Distance to Surface Water | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| 34. | Containment (Surface Water) | | |
| 35. | Surface Water Use | | |
| 36. | Distance to Sensi- tive Environment | | |
| 37. | Population Served (by Surface Water) | | , |
| 38. | Distance to Water Intake | | |
| 39. | Reactivity | | |
| 40. | Incompatibility | | |
| 41. | Toxicity (Air) | | |
| 42. | Population within 4 mile radius | - | |
| 43. | Land Use | | |
| | | | |